

GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Ken Fleck
OGM	Steve Demczak

Inspection Report

Permit Number:	C0150017 PARTIAL				
Inspection Type:					
Inspection Date:	Monday, September 12, 2011				
Start Date/Time:	9/12/2011 10:00:00 AM				
End Date/Time:	9/12/2011 1:00:00 PM				
Last Inspection:	Monday, August 15, 2011				

Inspector: Steve Demczak,

Weather: Sunny, 70's

InspectionID Report Number: 2862

Accepted by: jhelfric

9/14/2011

Permitee: **ENERGY WEST MINING CO**Operator: **ENERGY WEST MINING CO**

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	133.90
Total Disturbed	
Phase I	136.58
Phase II	95.70
Phase III	95.70

Mineral Ownership Types of Operations

✓ Federal
✓ Underground

State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demczak,
Inspector ID Number: 39

Date

Monday, Septemb



Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, September 12, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale			The property and	
2.	Signs and Markers	V		✓	
3.	Topsoil	~		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		~		
4.c	Hydrologic Balance: Other Sediment Control Measures	~		~	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation		V		
12.	Backfilling And Grading	✓		~	
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	Roads: Construction, Maintenance, Surfacing		~		
16.b	Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		~		
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, September 12, 2011

Page 3 of 3

2. Signs and Markers

The identification signs is located on the trail to the mine site.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function in a storm event. There were no signs of water erosion to the diversion.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment control.

8. Noncoal Waste

The area was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded to AOC standards in my opinion.

13. Revegetation

Vegetation is growing on the reclaimed area. Vegetation studies with giving detail how well the vegetation is doing and density.